Engineering Information

China Time Standard Standard

Useful 3-Phase Formulae

4. 8 Salas Ca

Phase current in 3-phase star= Line current

Phase current in 3-phase Delta=Line current/1.732

Engineering Information Engineering Information USEFUL 3-PHASE FORMULAE APPROXIMATE POWER CONSUMPTION OF **ELECTRICAL APPARATUS** Phase current in 3-phase star = Line current Phase current in 3-phase Delta = Line current/1.732 Kettles : h.p x 746 1 Slice 3 Slice 1 Pint KW - KVA x POWER factor = -1 Pint 324 to 425 W 1750 W 1000 x efficiency 2500 W 450 to 650 W 2 Pints 5 Slice 750 to 1000 W 1000 to 1500 Line amps x Line Volts; x 1.732 x p.f. 4-8 Pints Soldering Irons: Iron: 3 lb $KVA = \frac{}{pf.} = \frac{}{1000 \text{ x efficiency x p.f.}}$ 275 to 300 W 4 lb 1 lb 1.5 lb 350 to 450 W 450 to 500 W 200 W 275 W 2 lb 6 lb \$1 = Line amps x Line Volts x 1.732 500 to 650 W 3 lb 12 lb 600 to 700 W 1000 Imersion heaters 6 in long 200 to 500 W 500 to 750 W 800 to 1000 W 7 in long Line Volts x 1.732 p.f. Line Volts x 1.732 Drillling 9/16" hole 200 to 250 W 7/8" hole 350 to 400 1" hole 750 W 14 to 2000 W 16 in long perting too h.p. x 746 750 W 1500 W Ovens: 14 x 14 x 12 in inside 1500 W Line Volts x 1.732 x efficiency x p.f. 12 x 12 x 16 in inside 1750 W KW x 1000 x efficiency KVA x 1000 efficiency x p.f. 14 x 14 x 16 x in inside 2000 W Grinding : 6" x 3/4 " Wheel 8" x 3/4 Wheel Line amps x Line Volts x 1.732 x efficiency x p.f. 1250 W Vaccum Cleaner: 112 m betterougers astern dt 746 Hair drier High power 300 to 600 W h.p. x 746 x 100 mm/dl Line volts x p.f. x efficiency Pints Drop in 3-phase circuit = 1.732 x Line amps x Resistance of 1 core Watts